



PROJECT CASE STUDY

EDGE DRAIN

Project

Edge Drain
along curb
and road

Application

Highway Edge
Drain

Product

Hydraway
2000, 18"

Location

Sacramento,
CA

Year

2011-2012

Problem

Water was being built up along the island for 8 miles of street.

Solution

To prevent water from building up, Hydraway 2000 18" was to be installed along both sides of the island.

Result

There was no damage to road or the island by removing water build up.

Hydraway[®]

800-223-7015 | hydraway.net